

Black Light

Decontamination Inspection Tool

Introducing a new inspection method to ensure that all contaminated cleaner product is completely removed following the cleaning process.

Simply inspect surfaces with our exclusive black light lamp. Residual contaminated cleaner will be visible as a gold area or spot that can then be removed. With immediate inspection, you will be able to ensure the highest quality control and effective decontamination.



For additional product information, contact:

INTEGRATED CHEMISTRIES, INC.
P.O. Box 10558
White Bear Lake, MN 55110

Phone (651) 426-3224

Fax (651) 426-3114

Email info@integratedchemistries.com

Online: www.integratedchemistries.com

